

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

H.A.C. Incorporated
1124 West Ainsworth Avenue
Pasco, WA 99301

PMA No. PQ2131NM
Supplement 1
July 16, 2004
Amended May 31, 2005

<u>PART NAME</u>	<u>PART NUMBER</u>	<u>APPROVED REPLACEMENT FOR PART NUMBER</u>	<u>APPROVAL BASIS AND APPROVED DESIGN DATA</u>	<u>MAKE ELIGIBILITY</u>	<u>MODEL ELIGIBILITY</u>
Tail Rotor Blade Installation	HAC-47-3	Modification Part	STC SR09066RC, dated 5/22/96, MDL and Document List QA.001-47-400-2, revision 8, dated April 18, 2001 or later FAA approved revisions.	Bell	47, 47B, 47B3, 47D, 47D1, 47E, 47G, 47G-2, 47H-1, 47J, 47K, 47J-2, 47J-2A, 47G-2A, 47G-2A-1, 47G-3, 47G-3B, 47G-3B-1, 47G-4, 47G-4A, 47G-5, 47G-3B-2, 47G-5A & 47G-3B-2A

-----END OF LISTING-----

NOTE: Minor design changes (reference 14 CFR part 21 § 21.93 and § 21.95) must be submitted in a manner as determined by the ACO. Major design changes (reference 14 CFR part 21 § 21.93 and § 21.97) to drawings and specifications are to be handled in the same manner as that for an original FAA-PMA.



Wolf R. Caliebe, Manager
Seattle Manufacturing
Inspection District Office